# Chem 5390 Advanced X-ray Analysis

#### **LECTURE 15**

Dr. Teresa D. Golden University of North Texas Department of Chemistry

## **Diffraction Theory**

### **Diffraction Methods**

What can we learn from the diffractometer experiments? Phase Analysis Texture Analysis Lattice Parameters Crystallite Size Stress Analysis Strain Analysis



### **Precise Lattice Parameter Measurements**

Practical applications for lattice parameter measurements:

-determine composition (stoichiometry) of the sample

-determine thermal expansion coefficient



### **Precise Lattice Parameter Measurements**

Practical applications for lattice parameter measurements:

-determine composition (stoichiometry) of the sample

Since the samples are solids, the lattice parameter of a solid solution varies with concentration of the solute. So you can use accurate and precise lattice parameter measurements to calculate composition.



### **Precise Lattice Parameter Measurements**

Practical applications for lattice parameter measurements:

-determine thermal expansion coefficient

Thermal vibrations cause slight changes in interatomic spacing and corresponding changes in d-spacing.

Example: At 25°C,  $a_{AI} = 4.049$  Å and at 50°C,  $a_{AI} = 4.051$  Å.

thermal expansion coefficient,  $\alpha_{AI} = 23.6 \times 10^{-6}$ /°C



**Precise Lattice Parameter Measurements** 

High precision is possible at higher angles ( $\theta$ ).

**Example: For cubic system a**  $\infty$  d-spacing

Precision in a or d-spacing depends on precision in sin $\theta$  (derived from Bragg's law) not  $\theta$  (a measured quantity).



**Precise Lattice Parameter Measurements** 

The error in sin $\theta$  decreases as the value of  $\theta$  increases.

Example: At  $\theta$  = 45°, there is a 1.7% error for sin $\theta$ . At  $\theta$  = 85°, there is a 0.15% error for sin $\theta$ .

For this reason, precise lattice parameter measurements are done at 2θ values above 100°.



#### **Precise Lattice Parameter Measurements**



**Figure 13-1** The variation of  $\sin \theta$  with  $\theta$ . The error in  $\sin \theta$  caused by a given error in  $\theta$  decreases as  $\theta$  increases ( $\Delta \theta$  exaggerated).



### **Precise Lattice Parameter Measurements**

Without any extrapolation or attention to good experimental techniques, a precision of 0.01 Å can be reached when measuring at angles above 100° 20.

However, with good experimental techniques and use of various extrapolation functions, a precision of 0.001 Å can be obtained.

The actual  $\lambda$  value used must be explicitly stated. Cu K<sub> $\alpha 1$ </sub> = 1.540562 Å.

**Precise Lattice Parameter Measurements** 

In measurement of precise lattice parameters, must be aware of systematic and random errors.

<u>Systematic error</u> – varies in a regular manner with some particular parameter and always is the same sign.

**<u>Random error</u>** – ordinary chance errors and do not vary in any regular manner with position of  $2\theta$  and may be positive or negative.

Advanced 🗶-ray

Analysis

**Precise Lattice Parameter Measurements** 

In order to find the right extrapolation function, must know which effects are leading to error in the measurement of  $2\theta$ .



### **Precise Lattice Parameter Measurements**

The most common sources of systematic error in measuring dspacings are:

- 1. Misalignment of the instrument.
  - The center of the incident beam must intersect the diffractometer axis and the 0° position of the detector slit.

Advanced 🗶

chem 5390

-rav Analvsis

- 2. Use of a flat sample instead of curved to conform to the focusing circle. Minimized by decreasing the irradiation width of the sample.
- 3. Absorption in the sample.

Samples of low absorption should be made as thin as possible.

- 4. Displacement of the sample from the diffractometer axis. Usually the largest source of error.
- Vertical divergence of the incident beam.
  Minimize by decreasing the vertical opening of the detector slit.

### **Precise Lattice Parameter Measurements**

The most common sources of systematic error in measuring dspacings are:

- Use of a flat sample instead of curved to conform to the focusing circle.
  Minimized by decreasing the irradiation width of the sample.
- 3. Absorption in the sample.Samples of low absorption should be made as thin as possible.

#### $\Delta d/d$ varies as $\cos^2\theta$ for #2 and 3.

 $\cos^2\theta$  is Bradley-Jay function (only valid for diffraction peaks with  $\theta > 60^\circ$ ).



### **Precise Lattice Parameter Measurements**

The most common sources of systematic error in measuring dspacings are:

4. Displacement of the sample from the diffractometer axis. Usually the largest source of error.



### **Precise Lattice Parameter Measurements**

The most common sources of systematic error in measuring d-spacings are:

4. Displacement of the sample from the diffractometer axis. Usually the largest source of error.

 $\Delta d/d$  varies as  $\cos^2\theta/\sin\theta$  for #4.

Vertical divergence of the incident beam.
 Minimize by decreasing the vertical opening of the detector slit.

 $\Delta d/d$  varies as  $[\cos^2\theta/\sin\theta + \cos^2\theta/\theta]$  for #5.

 $[\cos^2\theta/\sin\theta + \cos^2\theta/\theta]$  is Nelson–Riley function for Hull/Debye-Scherrer camera

Advanced 📕

chem 5390

-rav Analysis

**Precise Lattice Parameter Measurements** 

Bradley-Jay method Plot of lattice parameter versus cos<sup>2</sup>θ

anced

Nelson-Riley method Plot of lattice parameter versus cos<sup>2</sup>θ/sinθ + cos<sup>2</sup>θ/θ

Extrapolate plot to  $\theta = 90^{\circ}$ 

### **Precise Lattice Parameter Measurements**

What you need to do to get the best answer:

- 1. Use the actual  $\lambda$  value in your calculations. Cu K $\alpha$ 1 = 1.540562 Å.
- 2. Obtain as many reflections as possible in the high-angle region. Can decrease the I of radiation by using Mo K $\alpha$  instead of Cu K $\alpha$ .
- 3. When  $\alpha_1$  and  $\alpha_2$  are resolved, use both points in your graph.
- 4. Obtain line positions as precisely as possible.
  - Use step scanning mode. Find the centroid.



### **Precise Lattice Parameter Measurements**

What you need to do to get the best answer:

4. Obtain line positions as precisely as possible. Use step scanning mode. Find the centroid.

Methods for determining peak position:

- 1. Maximum intensity
- 2. Center of gravity
- 3. Projection
- 4. Gaussian
- 5. Lorentzian



### **Precise Lattice Parameter Measurements**

Methods for determining peak position:

1. Maximum intensity



### **Precise Lattice Parameter Measurements**

Methods for determining peak position:

- 4. Gaussian
- 5. Lorentzian

Pseudo-Voigt which lies between gaussian and lorentzian generally works well.





### **Precise Lattice Parameter Measurements**

Methods for determining peak position:

Accuracy is critical, to know the lattice parameter to within 1 x 10<sup>-5</sup> nm, must know the peak position to within 0.02° at  $2\theta = 160^{\circ}$ .



**Precise Lattice Parameter Measurements** 

Noncubic crystals are more difficult.

Example: For hexagonal or tetragonal, the hkl represents the lattice parameters a and c.

However can use hk0 line to find value of a only.

Alternatively, the best method is the Cohen analytical method.

Advanced 🗶

-rav Analysis

**Precise Lattice Parameter Measurements** 

Bradley-Jay and Nelson-Riley are designed for systematic errors.

For random errors, the Cohen method can be used for cubic and noncubic systems. The Cohen method is a least-squares method.



**Precise Lattice Parameter Measurements** 

Cohen method

For cubic system combining Bragg equation and d-spacing equation, for any diffraction peak:

$$\sin^2\theta(true) = \frac{\lambda^2}{4a_o^2} \left(h^2 + k^2 + l^2\right)$$

 $a_o$  is the true lattice parameter.



### **Precise Lattice Parameter Measurements**

#### **Cohen method**

 $\sin^2\theta(observed) - \sin^2\theta(true) = \Delta \sin^2\theta$ 



chem 5390

Advanced 🗶-ray Analysis

C = D/10 and  $\delta = 10 \sin^2 2\theta$ 

**Precise Lattice Parameter Measurements** 

**Cohen method** 

sin<sup>2</sup> $\theta$  and  $\alpha$  are known from indexing the diffraction pattern and from  $\delta$ .

A and C are determined by solving two simultaneous equations for the observed reflections. The true value of the lattice parameter can then be calculated.

Combine Cohen's method with the least squares method to minimize observational errors.

Advanced 🗶-ray Analysis

### **Precise Lattice Parameter Measurements**



**Figure 13-3** Extreme forms of extrapolation curves (schematic): (a) large systematic errors, small random errors; (b) small systematic errors, large random errors.

Advanced

nalysis

**Precise Lattice Parameter Measurements** 

Systematic errors in a (lattice parameter) approach zero as  $\theta$  approaches 90°, and are eliminated with extrapolation.

Magnitude of error  $\infty$  slope of line. Small errors lead to flat lines. Random errors in a also decrease in magnitude as  $\theta$  increases.



#### **Precise Lattice Parameter Measurements**



XRD Pattern for Al

chem 5390

Advanced X-ray Analysis

CuKa

#### **Precise Lattice Parameter Measurements**





#### **Precise Lattice Parameter Measurements**

Kα <sub>1</sub>	Kα <sub>2</sub>									
1.54056	1.54439									
Peak	20	θ	sin²θ	adjusted	h	k	ī	а	cos²θ /sin θ	cos²θ
1	111.83	55.92	0.68593	0.68593	3	3	1	4.05403	0.379220	0.314073
2	112.25	56.13	0.68932	0.68591	3	3	1	4.05408	0.374193	0.310676
3	116.36	58.18	0.72200	0.72200	4	2	0	4.05409	0.327165	0.277995
4	116.82	58.41	0.72559	0.72200	4	2	0	4.05410	0.322141	0.274405
5	137.13	68.57	0.86645	0.86645	4	2	2	4.05399	0.143474	0.133550
6	137.86	68.93	0.87075	0.86644	4	2	2	4.05401	0.138506	0.129246

$$\sin^2 \theta_{K\alpha 1(\mathrm{adj})} = \sin^2 \theta_{K\alpha 2} \left( \frac{\lambda_{K\alpha 1}^2}{\lambda_{K\alpha 2}^2} \right)$$

chem 5390

Advanced 🗶-ray Analysis

#### **Precise Lattice Parameter Measurements**

				adjusted										
Pe	eak	θ	sin <sup>2</sup> 0	sin²(θ)	h	k	1	α	δ	α <sup>2</sup>	αδ	δ <sup>2</sup>	αsin²(θ)	δsin²(θ)
	1	55.92	0.68593	0.68593	3	3	1	19	8.6	361	163.7	74.26	13.03261	5.91080
1	2	56.13	0.68932	0.68591	3	3	1	19	8.6	361	162.8	73.38	13.03228	5.87567
	3	58.18	0.72200	0.72200	4	2	0	20	8.0	400	160.6	64.46	14.44010	5.79665
4	4	58.41	0.72559	0.72200	4	2	0	20	8.0	400	159.3	63.43	14.44000	5.75021
4	5	68.57	0.86645	0.86645	4	2	2	24	4.6	576	111.1	21.42	20.79479	4.01044
(	6	68.93	0.87075	0.86644	4	2	2	24	4.5	576	108.0	20.26	20.79457	3.90042

Σ 2674 865.5 317.21 96.53435 31.24421



 $\alpha = h^2 + k^2 + l^2$  $\delta = 10\sin^2 2\theta$ 



### **Precise Lattice Parameter Measurements**

Can use lattice parameters for phase diagram determinations also.

Phase diagrams establish what phases are present at different temperatures, pressures, and compositions of an alloy system.

Phase diagrams can be very complex.



### **Precise Lattice Parameter Measurements**

#### Common terms associated with phase diagrams:

- Continuous solid solution

Complete mixing of components. Components must have the same crystal structure. Crystal structure does not change through solubility range.

- Primary (terminal) solid solution
  - Partial solubility of components in each other. Depends upon atomic size. Go beyond solubility limit for  $\alpha$  and  $\beta$  will precipitate.  $\alpha$  has different crystal structure than  $\beta$ .
- Intermediate solid solution or Intermediate phase

Intermediate solid solution or phase almost always has different crystal structure than the phases on either side of it.

#### Advanced X-ray Analysis

chem 5390

### **Precise Lattice Parameter Measurements**

#### To determine a phase diagram with X-ray diffraction: For a binary systems (procedures for ternary systems are similar)

- 1. Prepare alloys at definite composition intervals from pure elemental constituents.
- 2. Equilibrate alloy at the desired temperatures.
- 3. Collect and index XRD patterns.
- 4. Look at how the calculated lattice parameters vary with composition and temperature.



#### **Precise Lattice Parameter Measurements**



Figure 1: Representative examples of phase diagrams showing (a) complete solid solubility, (b) partial solid solubility, (c) and (d) partial solid solubility along with the formation of an intermediate phases.



#### **Precise Lattice Parameter Measurements**



Figure 2: Phase diagram and lattice constants of a hypothetical alloy system. Adapted from Cullity and Stock, <u>Elements of X-ray Diffraction</u>, 3<sup>rd</sup> Edition (Prentice Hall, Upper Saddle River, NJ) p. 334.



### **Precise Lattice Parameter Measurements**



Figure 6. Cuprite structure for Cu<sub>2</sub>O. Copper atoms are represented by small light spheres and oxygen atoms are represented by large dark spheres. (a) Copper special positions at (0.25, 0.25, 0.25); (0.75, 0.75, 0.25); (0.75, 0.25, 0.25); (0.75, 0.75, 0.25); (0.75, 0.75, 0.75) and oxygen special positions at (0, 0, 0); (0.5, 0.5, 0.5); (0, 50, 0.5); (0, 0, 0, 0); (0.5, 0.5); (0, 0, 0, 0); (0.5, 0.5); (0, 0, 0); (0.5, 0.5); (0, 0, 0); (0.5, 0.25); (0.75); (0.25, 0.25); (0.75); (0.25, 0.25); (0.75); (0.25, 0.25).



**Figure 5.** Rietveld analysis for powder produced by grinding several films deposited at 65 °C and E = -0.45 V. Powder X-ray data (solid line), Rietveld fit (crosses) and difference pattern (solid line shown below data) are shown for Cu<sub>2</sub>O.



### **Precise Lattice Parameter Measurements**





Advanced X-ray Analysis

### **Precise Lattice Parameter Measurements**



Advanced -ray Analysis

### **Precise Lattice Parameter Measurements**



FIG. 1. The fcc cell of  $CeO_2$  with the fluorite structure.



Advanced X-ray Analysis

### **Precise Lattice Parameter Measurements**



nalvsis

**Precise Lattice Parameter Measurements** 



Advanced

chem 5390

vsis

### **Precise Lattice Parameter Measurements**





Advanced X-ray Analysis

Lab 4 – Due today

Lab 5 – Due 11-30-21

**Reading Assignment:** 

Read Chapter 8 from: -X-ray Diffraction Procedures by Klug and Alexander

Read Chapter 13 from: -Elements of X-ray Diffraction, 3<sup>rd</sup> edition, by Cullity and Stock